

**On-car analysis list from October 31st, 2022**  
**please contact VW Helpline before attempting repair**

	<b>Models</b>	<b>MY</b>	<b>Engine</b>	<b>Transmission</b>	<b>Topic</b>	<b>Customer Complaint</b>
<b>Powertrain</b>	Atlas, Atlas Cross Sport	21-22	All	All	Heat Shield Rattle	Customer states rattle noise from the underbody heat shields
	Taos	22	All	All	MIL-on P0456 P0442	Customer states MIL-on, fault P0456 and/or P0442 stored in ECM memory <b>(Reference worksheet "Tiguan EVAP Leak Worksheet" before creating/calling Group TAC)</b>
<b>Electric</b>	Atlas, Atlas Cross Sport	20-22	All	All	Lane Assist	Customer states blind spot monitoring error in MFI <b>(untouched vehicles)</b> <b>(Must have faults code C1114F0 and/or C1115F0 in 3C module)</b> <b>(Reference worksheet "VIN4PIN_Lane_Change_Assist_Errors" before creating/calling Group TAC)</b>
	Tiguan (2019 only), Golf, Sport Wagon, Jetta (2019 only)	18-19	All	All	Door Harness	Customer states MIL-on/Airbag light, fault U019900 and/or B101715 stored in ECM/Airbag memory
	Atlas, Atlas Cross Sport	20-23	All	All	Airbag light on Fault B1225F1	Customer states Airbag light on <b>(Must have fault code B1225F1)</b>
	Atlas, Atlas Cross Sport, Jetta, Taos, Tiguan	22	All	All	KESY Door Lock/Unlock Inoperative	Customer states KESY door lock/unlock inoperative <b>(Untouched vehicles)</b> <b>(Must have fault codes B1479F0 and/or B147AF0 in AW 09)</b>
	Tiguan	22-23	All	All	Seat Belt	Customer states seat belt won't retract
	Taos	22	All	All	Windshield	Customer states there is a visual imperfection in the windshield <b>(Untouched vehicles)</b>