

Unit Injector Rocker Arm Service Instructions

M-214-003

(December 2008)

Valid for

Mack CXU, CHU, GU, MRU, LEU models with an MP7 and EM-USA07 emissions

Case description

If spalling is noted on one or more unit injector cam lobes and/or unit injector rocker arm rollers during service or repair of the valve train on a US07 MP7 engine, it is mandatory that the repair includes replacement of all six unit injector rocker arms with the most current part number (part number 21266310).

Note: Does not apply to Mack Trucks Australia.

Issued by

Technical Service

Mack Trucks, Inc. engages in a continuous program of testing and evaluating to provide the best possible product. Mack Trucks, Inc., however, is not committed to, or liable for updating existing chassis.