

Subject: Engineering Information - Service AWD Lamp Illuminated On Driver Information Center (DIC), DTCs C1260, C1261, C1262, C1263, C1264, C1265, C1266, C1267, C1290, C1291, C1292, C1293, C1295 and/or C1296 Set

This PI has been revised to end the need for gathering information from the field. Please discard PIE0699.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2021	2023	—	—	Equipped with 3.6L Engine (RPO LFY)	Equipped with 9 SPD Transmission (RPO M3W)
Cadillac	XT5	2021	2023	—	—	Equipped with 3.6L, 2.0L Engine (RPOs LGX, LSY)	Equipped with 9 SPD Transmission (RPOs M3W, M3G)
	XT6						Equipped with 9 SPD Transmission (RPOs M3V, M3T)
Chevrolet	Blazer						
	Traverse					Equipped with 3.6L Engine (RPO LFY)	Equipped with 9 SPD Transmission (RPO M3V)
GMC	Acadia					Equipped with 3.6L, 2.0L Engine (RPOs LGX, LSY)	Equipped with 9 SPD Transmission (RPOs M3W, M3G)

Correction

GM engineering is ending the need for gathering information from the field and no longer needs to be contacted. If you encounter a vehicle with the above concern, follow normal diagnostics in SI or refer to bulletin 22-NA-006.

Version	2
Modified	Released May 13, 2022 Revised October 19, 2022 - Ended the need for gathering further information from the field.