

BODY & CHASSIS

Rear Quarter Glass Finisher Abrasion Marks Below Tailgate Spoiler

23MY New Range Rover Sport (L461)

Customer Voice:

- A customer may report abrasion marks (scuffing) on the quarter glass finisher when the tailgate is open.

Technical Description:

- This may be caused by the rear spoiler winglet seals contacting the finisher when the tailgate is closed.

Status:

- SSM 75864 has been published to address this concern by removing the winglet seals.
- The abrasion marks on the finisher should easily be removed with suitable polish.

