

Service Bulletin

INFORMATION

Subject: Information on Malfunction Indicator Lamp (MIL) Illuminated – Multiple Transmission DTCs Set

Attention: This bulletin is to advise the technicians of a new transmission service diagnostic test. This bulletin will become obsolete at a later date.

Note: If DTC P1955 or P0867 is set, please proceed to the latest version of PIP5797 for direction.

Brand:	Model:	Model Year:		VIN:		Engine	Transmission
		from	to	from	to	Engine:	Transmission:
Chevrolet	Corvette	2020	2023	—	—	—	—

Involved Region or Country	North America, Europe, Middle East, Japan, Australia/New Zealand		
Condition	Some customers may comment that the MIL is illuminated. Technicians may find one or more of the following DTCs set in the Transmission Control Module (TCM): P0747, P0746, P0777, P0776, P2809, P2808, P2724, P2723, P0797, P0796, P2715, P2714, P2818, P2817, P08C5, P08C4, P27BA, P27B9, P27C2, P27C1, P27CA, P27C9, P27D2, P27D1, P282A, P2829, P1956, P1957, P1958, P1959, P2735, P18A8, P18A9, P2821, P2820, P187D, P187E, P2855, P2853, P2856, P2854, P0869, P0868, C2A18, C2A19, P0844, P0841, P0849, P0846, P0874, P0871, P0879, P0876, P1946, P1947, P1948, P1949, P194A, P1961, P194B, P194C, P194D, P194E, P073F, P074A, P074B, P074C, P074D, P074E, P074F, P07D8, P073E, P194F and/or P1950.		
Cause	This condition may be caused by an Internal transmission solenoid or switch sticking due to debris.		
Information	If any of the P-codes are set, perform a transmission service diagnostic test. Refer to <i>Transmission Service Diagnostic Test</i> in the Service Manual.		

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Page	2
гауе	~

Version	6
	Released February 12, 2021
	Revised June 28, 2021 – Added a Note at beginning of Service Procedure and new GDS information to steps 8 and 9.
	Revised December 07, 2021 – Added a Note under the Subject, the 2022 Model Year, DTC P1961 to Condition section, updated the Involved Region or Country section and updated information under step 10 and Parts Information.
Modified	Revised December 15, 2021 – Updated the Service Procedure.
	Revised July 29, 2022 – Added the 2023 Model Year, Removed P1955 and P0867 from Condition and Correction sections, Changed And to Or in bold text in Correction section and Added an Important statement above the Service Procedure.
	Revised November 10, 2022 – Added Attention statement, removed Correction section to add an Information section, removed the Service Procedure, Parts Information and Warranty Information sections.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION