



Technical Service Bulletin

Technical Service Bulletin: TSB220213

Released Date: 08-Nov-2022

Visible Engine Vapor Observed at Crankcase Breather Vent Tube

Visible Engine Vapor Observed at Crankcase Breather Vent Tube

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- L9 CM2450 L126B

Issue Summary

Symptom:

- Equipment experiencing visible engine vapor at crankcase breather vent tube

Root Cause:

- Vapors can escape the crankcase breather vent tube because of the design change to maintenance-free impactor breather on model year 2021 L9 CM2450.

Verification

- Verify that no visible liquid drips from the crankcase breather vent tube.

Resolution

No action required.

Document History

Date	Details
2022-10-18	Module Created

Date	Details
2022-11-7	Removed statement about km and mile restrictions.

Last Modified: 08-Nov-2022
