



Preliminary Information

PIT5942A Information On Vehicle Option Retrofits Due to The Chip Shortage.

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Encore GX	2022	All	All	All	All
Buick	Enclave	2022	All	All	All	All
Buick	Envision	2022	All	All	All	All
Cadillac	XT4	2022	All	All	All	All
Cadillac	XT5	2022	All	All	All	All
Cadillac	XT6	2022	All	All	All	All
Chevrolet	Blazer	2022	All	All	All	All
Chevrolet	Equinox	2022	All	All	All	All
Chevrolet	Malibu	2022	All	All	All	All
Chevrolet	Silverado 1500 LTD (RPO J21, VIN Digit 5 = W / Y)	2022	All	All	All	All
Chevrolet	Silverado 2500HD/3500HD	2022	All	All	All	All
Chevrolet	Trailblazer	2022	All	All	All	All
Chevrolet	Traverse	2022	All	All	All	All
GMC	Acadia	2022	All	All	All	All
GMC	Sierra 1500 Limited (RPO J21, VIN Digit 5 = 8 / 9)	2022	All	All	All	All
GMC	Sierra 2500HD/3500HD	2022	All	All	All	All
GMC	Terrain	2022	All	All	All	All

Involved Region or Country:	North America
Additional RPO/s:	00R, 00V, 00Z, 04O
Condition:	Cannot complete or program component retrofit.
Cause:	Retrofit for your particular vehicle may not be released yet.

Correction:

TAC is receiving calls for assistance on retrofits not yet released .

The deleted options will be retrofitted through several bulletin releases.

These are being launched based on option, parts availability, trim level and model.

If you are presented a vehicle for retrofit and there is not an open bulletin listed in VIS for this vehicle VIN do NOT attempt the retrofit.

You will not receive the correct components and the proper calibrations to function them will not be attached to your VIN in SPS.

Additional SI Keywords

disable, disabled, front, heat, heated, inop, inoperative, missing, module, rear, row, seat, seats, switch, vent, vented, ventilation,

Version History

Version	2
Modified	09/08/2022 - Created on. 11/08/2022 - Updated to add models.



© 2022 General Motors. All Rights Reserved.