

# N763 H426 – P6 ENGINE CAMSHAFT CARRIER HOLE



## UPDATE PRIOR TO SALE N763 H426 – P6 CAM CARRIER HOLE

AFFECTED MODELS	23MY New Range Rover, New RR Sport, RR Velar, Discovery and Defender 23MY F-PACE
VOLUME AFFECTED	LR USA 6441 CAN 417      JAG USA 228 CAN 10
REPAIR	On certain 23MY vehicles, a concern has been identified where an engine Camshaft Carrier hole has not been fully drilled. Affected vehicles will require an inspection to confirm which engines will need a repair. Vehicles that pass inspection may proceed through to sale.
REPAIR TIME	Inspection, 0.1hrs +DIDO    Engine Repair is TBA
CAMPAIGN LAUNCH	Land Rover December 5th, 2022 (Inspection procedure), Jaguar Dec 6 <sup>th</sup> , 2022 (Quarantine instruction, Inspection to follow) Engine Repair Bulletin – TBA
Notes	There are c.500 affected vehicles in retailer inventory. Please check the Warranty Portal or BBSS inventory reports for any affected VIN at your store. These vehicles must be held from sale until the vehicles pass inspection or have an engine repair completed.