



# RCA-56-22-011-1: Replace Bed Storage Compartment Seal

Rivian is initiating a customer satisfaction campaign for some model year 2022 R1T vehicles that have a bed storage compartment that could be difficult to open during freezing weather conditions. In these conditions, the bed storage compartment seal could stick to the bed floor panel if moisture seeps between these components and freezes. Rivian will replace the bed storage compartment seal with a new seal that is coated to prevent sticking. Rivian is launching this campaign for customer satisfaction and to ensure the quality of Rivian vehicles.

<b>Document Type</b>	Customer Satisfaction Campaign Bulletin
<b>Date</b>	December 12, 2022
<b>Affected Region(s)</b>	USA
<b>Affected Model(s)</b>	R1T
<b>Model Year(s)</b>	2022
<b>Approximate Build Dates</b>	August 2021 - May 2022
 Refer to the FSA Dashboard to determine if this document applies to a specific vehicle.	
<b>Vehicle System</b>	56 - Closures
<b>Minimum Service Location</b>	Mobile

## Required Parts

Part Number	Quantity	Engineering Name	Service Name/Notes
PT00002343-E	1	BULB SEAL - REAR BIN	Seal, Bed Storage Compartment

 **Attention:** The parts listed in this table are only for unique steps that are called out in this bulletin. Some sections of this bulletin might refer to Service Manual procedures which require additional parts. Always review the bulletin and all potentially related Service Manual procedures before ordering parts and beginning work.

## Procedure

Replace: Seal, Bed Storage Compartment (refer to service manual procedure 568020010).

## Labor Codes

Labor Code	Description
RCA562201100	RCA-56-22-011 not applicable
RCA562201101	Replace the bed storage compartment seal
Contact <a href="mailto:ServiceDocumentFeedback@rivian.com">ServiceDocumentFeedback@rivian.com</a> regarding labor codes and document content.	