

#### 66 Front radiator grille trim incorrect for the vehicle

66 22 93 2068096/2 December 21, 2022. Supersedes Technical Service Bulletin Group 66 number 22-92 dated September 28, 2022, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q8, SQ8, and RS Q8	2023	000001 – 003082	Not Applicable

## Condition

REVISION HISTORY					
Revision	Date	Purpose			
2	-	Revised Condition (specific paint codes and color descriptions added)			
		Revised <i>Technical Background</i> (specific paint codes and color descriptions added)			
		Revised Service (specific paint codes and color descriptions added)			
		Revised Warranty (paint procedure removed [no longer required])			
		Revised Required Parts and Tools (Grille trim part number change)			
1	09/28/2022	Initial publication			

#### Customer states:

The trim that surrounds the radiator grille is the incorrect color for the intended build configuration of the vehicle.


#### Workshop findings:

The error in production regarding the radiator grille trim color installed is confirmed (e.g. LY9B Brilliant Black trim intended, L1RR Platinum Grey installed).

### **Technical Background**

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.


# **Technical Service Bulletin**



The trim that surrounds the front radiator grille installed in production is L1RR Platinum Grey instead of the intended LY9B Brilliant Black trim.

Figure 2 shows the correct configuration with a

LY9B Brilliant Black radiator trim.



*Figure 1.* L1RR Platinum Grey radiator grille trim installed. LY9B Brilliant Black trim intended.



*Figure 2.* Correctly configured radiator grille trim in LY9B Brilliant Black.


# **Production Solution**

The production process has been corrected.

© 2022 Audi of America, Inc.

Page 2 of 4

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



### Service

Replace the radiator grille trim with the correct LY9B Brilliant Black trim.

## Warranty


Claim Type:	910 Before Delivery.					
	• 110 up to 6 Months/6,000 Miles.					
	• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.					
Service Number:	6605					
Damage Code:	0012					
Labor Operations:	Front trim remove and reinstall (base configuration)	6601 1900	See SRT with associated operations			
	-or-					
	Front trim remove and reinstall (with parking aid)	6601 1902	See SRT with associated operations			
	-or-					
	Front trim remove and reinstall (with night vision camera, overhead view camera, radar sensor and parking aid)	6601 1904	See SRT with associated operations			
	-or-					
	Front trim remove and reinstall (RSQ8)	6601 1905	See SRT with associated operations			
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)			
	Road test prior to the service procedure	No allowance	0 TU			
	Road test after the service procedure	0121 0004	10 TU			
Claim Comment:	As per TSB 2068096/2					
All	provide the providence with the independence with the					

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

© 2022 Audi of America, Inc.

Page 3 of 4

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



# **Required Parts and Tools**

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.				
Part Number	Part Description	Quantity		
4M8807725 Y9B	Contraction of the contraction o	1		
	Radiator grille trim including cover for towing eye in LY9B Brilliant Black			

# **Additional Information**

All parts and service references provided in this TSB (**2068096**) are subject to change and/or removal. ©**2022 Audi of America, Inc.** All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

© 2022 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.