



## STAR ONLINE PUBLICATION



**Case Number:** S2223000026

**Release Date:** March 2022

**Symptom/Vehicle Issue:** Front Tire Rub On Fender Liner Splash Shield



**Discussion:** If a customer states there is a rubbing, clunking, or rattle noise on tight turns while cornering, inspect the above area for signs of contact with the tire. If rub marks exist on the splash shield it is not necessary to replace it. Using hand pressure over bend and adjust the shield away from the tire in the diagonal area shown in the image below.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**



## STAR ONLINE PUBLICATION



Once the adjustment is completed test the fitment by turning to each steering lock to confirm the improvement in clearance.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**