



Technical Service Bulletin

Technical Service Bulletin: TSB220177	Released Date: 23-Aug-2022
New Injector Grommet Seal	

New Injector Grommet Seal

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B4.5 CM2350 B129B
- B4.5 CM2350 B147B
- B4.5 CM2620 B158B
- F3.8 CM2350 F120B
- F3.8 CM2350 F132B
- F3.8 CM2620 F137B
- F4.5 CM2620 F139B
- ISB4.5 CM2350 B104
- ISF3.8 CM2220 F103
- ISF3.8 CM2220 F110
- ISF3.8 CM2220 F116
- ISF3.8 CM2220 F134B
- ISF3.8 CM2350 F109
- ISF4.5 CM2220 F123
- QSF3.8 CM2350 F107
- QSF3.8 CM2350 F118
- QSF3.8 CM2350 F119

Description of Change

This document announces the new injector grommet seal for valve cover options:

- VC 9532
- VC 9697
- VC 9789
- VC 9592

- VC 9614
- VC 9894
- VC 9898
- VC 9895
- VC 9899
- VC 9896
- VC 9900
- VC 9897
- VC 9901

Reason for Change

There were lubricating oil leaks observed on the injector fuel line, as well as problems with fuel line misalignment.

Service Parts

Service parts are offered. See Table 1 for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Injector Grommet Seal	5301652	No	No	5562909

Document History

Date	Details
2022-8-18	Module Created

Last Modified: 23-Aug-2022

<https://cst.cummins.com>
<http://edsprod.cummins.com>
<https://gpst.cummins.com>
<https://quickserve.cummins.com>
<https://parts.cummins.com>
<https://store.cummins.com>
<https://wwsps.cummins.com>
<https://access.cummins.com>
<https://commerce.cummins.com>
<https://qsservices.cummins.com>
<https://webparts.cummins.com>
<https://qsservices.cummins.com>
<https://adminportal.cummins.com>
<0sp4N000000PGNq>
<https://cumminscommerce.force.com>
<https://mylogin.cummins.com/web/idp/login>