



NUMBER: 03-003-22

GROUP: 03 - Differential and Driveline

DATE: July 14, 2022

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

SUBJECT:

Front or Rear Axle Sensor Kit

MODELS:

2018 - 2022	(JL)	Jeep Wrangler
2020 - 2022	(JT)	Jeep Gladiator

NOTE: This Informational bulletin applies to vehicles equipped with Tru-Lok Front & Rear Axles (Sales Code DSE).

DISCUSSION:

A service kit (Sensor Kit, Axle: 68544629AA) is available to repair the Axle Locker Sensor on the vehicles equipped with both the M210 and M220 Tru-Lok axles (Sales Code DSE). This parts kit must be used when the Axle Locker Sensor fails. **Do not replace the Front or Rear Axle assemblies.** Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info>03 - Differential and Driveline / Sensors / Removal and Installation / Axle Locker Sensor.

NOTE: Customers may comment on a Service Axle Locker message displayed in the Electronic Vehicle Information Center (EVIC) for this condition.

POLICY:

Information Only