

Preliminary Information

PIT5961 Service Park Assist Message

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to	Eligille.	Transmissions.
Chevrolet	Blazer	2023	October 18 2023	October 19 2023	All	All

Involved Region or Country	North America
Additional Options (RPO)	060
Condition	A vehicle may be encountered with a "service park assist" message. Upon further investigation it will be found that the vehicle is built with RPO 060- Not equipped with park assist
Cause	Software

Correction:

Do not perform any repairs at this time.

Updated calibrations will be available 12/12/2022.

On or after that date perform the following IPC programming steps.

- 1. Program the Instrument Cluster
- 2. Setup and Configure the Instrument Cluster
- 3. Perform the USB file transfer

All programming steps need to be completed. Refer to SI for exact procedure for the vehicle that you are working on.

<u>Version History</u>

Version	1
Modified	12/06/2022 - Created on.

















GENERAL MOTORS