

Bulletin No.: PIT5940B **Published date:** 12/12/2022

Preliminary Information

PIT5940B Rear View Camera Display Gridlines Dim

<u>Models</u>

Brand:			VIN:		_	_	
	Model:	Model Years:	from	to	Engine:	Transmissions:	
Buick	Envision	2021 - 2023	All	All	All	All	
Involved Region or Country		United States, Canada, Mexico, Europe, Uzbekistan, Russia, Middle East, Israel, Palestine, Argentina (Mercosur), Brazil (Mercosur), Bolivia (West), Chile (West), Colombia (West), Paraguay (West), Peru (West), Uruguay (West), Japan, Cadillac Korea (South Korea), Gm Korea Company, Thailand (ASEAN), Australia/New Zealand, Other Africa					
Additional Options (RPO)		IOS, IOT or IOU with UVB					
Condition	a T	ome customers may compland hard to see. hey may mention that this s DTA)	seems to ha	ave sta	rted after they		
Cause	т	his is due to a software ano	maly.				

Do not attempt any repairs at this time. Engineering is working on a solution. This PI will be updated or a bulletin will be released when a repair becomes available.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Time
3487618	Thin or dim grid lines on display after V160 update	0.2 Hrs.

Additional SI Keywords

grid, grid-lines, guide, guide-lines, guidelines, line lines,

Version History

Version 3	
	08/26/2022 - Created on.
Modified	10/17/2022- Updated to add model year 2023 per BQM, David Lotsof 12/12/2022- Removed all models except Envision per Bill Taylor- bulletin # 22-NA-250 released for all other models



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.