Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

instrum

DESCRIPTION:

*New markets added.

If the customer claims that they are unable to recieve software updates available via OTA, the problem might be that the "certificates" for the TCAM and IHU might be invalid.

Page 1 of 2

If so, follow the advice under SERVICE.

PS = Polestar OTA = Over The Air TCAM = Telematics and Connectivity Antenna Module IHU = Infotainment Head Unit

CSC Customer Symptom Codes

Code	Description					
2L	Service/repair/Courtesy car					
52	Remote update/Does not work					
2V	Technician information/Software/Vehicle communication/Not for warranty use					

Technical Journal 35928.4.0

DTC Diagnostic Trouble Codes

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
534							2021-9999		0000001-0999999	202007-999952

SERVICE:

To download new certificates:

- 1. If there is a TOTAL UPGRADE available in VIDA, perform a software upgrade in accordance with TJ 35361.
- 2. Download new certificates by searching for and downloading "CHANGE MARKET CERTIFICATES" (P/N 32264753) under the Software Installation tab.

Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, please use following data: VST OP number: 36004-2 & 36002-3 & CSC 52

VST Operation Number

VST Operation Number	Description					
36004-2	Software control module downloading					
36002-3	Additional Software control module downloading					

LABOR TIME:

Labor time subject to change without notice.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report Polestar" and sub concern area "Support needed Polestar", use function group 3000.

Page 2 of 2 2022-12-15