Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

If experiencing any of the below described symptoms (mainly DAB functions), please seeadvice under "Service".

Symptoms:

- Pictures and text from radio stations are shown with delay
- Pictures and text from radio stations stops updating
- At startup, radio play different radio station than last used
- List of radio stations and favorites is empty (DAB and FM)
- SiriusXM channel information is not updating but playing selected station(s)

IHU = Infotainment Head Unit DAB = Digital Audio Broadcasting

CSC Customer Symptom Codes

Code	Description						
7W	Radio/Interference/FM and DAB						
DP	Radio/Does not work						
FE	Radio/Setting frequency (station or pre-set) does not work						
HQ	Radio/Poor reception/FM and DAB						

Technical Journal 36379.2.0

DTC Diagnostic Trouble Codes

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	l Chassis range	Struc Week Range
534							2021-9999		0000001-9999999	202007-999952

SERVICE:

*Software improvements for symptoms described under "description" have been released under software V2.5. If an earlier software version exists, please perform a Total Upgrade in accordance with TJ 31543.

Warranty claim info:

Note that the TJ number must be stated in repair order text.

To get a warranty claim accepted for a job described in this TJ, please use following VST OP number: 36004-2

Failing Part: No part replacement accepted

VST Operation Number

VST Operation Number	Description				
36004-2	Software control module downloading				

LABOR TIME:

0.5

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report Polestar" and sub concern area "Support not needed Polestar", use function group 3910.

Page 2 of 2 2022-12-08