



91-23-01TT - RNS 510 Navigation Radio Volume Knob Outer Ring Separated  
- Service Part Available

Release date: 1/26/2023

## Condition

**ATTENTION:**

**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.  
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

### Applicable Vehicles

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All	2009 - 2016	All	All	All	All

### Revision Table

Instance Number	Published Date	Version Number	Reason For Update
2069302/1	1/26/23	91-23-01TT	Original publication.

## Technical Background

The customer may complain that the outer plastic ring on the RNS 510 (PR code 7UL) Volume Knob/Power Button has separated and/or has fallen off the knob (Fig. 1).



Figure 1.

## Service

The RNS 510 Volume Knob/Power Button is now a part that is available separately.

**Part No: 5C0998922** (RNS 510 Volume Knob)



**91-23-01TT - RNS 510 Navigation Radio Volume Knob Outer Ring Separated  
- Service Part Available**

Release date: 1/26/2023

---

## Additional Information

© 2023 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.