

Staining/Surface Damage on Door Trim Bars and Side Window Trim Element

Topic number	LI72.00-P-075743
Version	1
Function group	72.00 - General
Date	1/4/23
Validity	Model 205.0/2
Reason for change	

Complaint

Staining on door trim strips and top and bottom trim elements on rear side windows. See example pictures 1, 2 and 3.


Attachments	
File	Description
Bild 2.jpg 	Example of complaint relating to door upper trim strip in silver look
Bild 3.jpg	Example of door trim bar complaint on models with code P59 Black optics



Bild 1.JPG



Cause

Damage to protective coating of door beltline trim strips, door upper trim strips and side window trim element.

Remedy

1. Check if the problem cannot be rectified by polishing the trim bars with the polishing paste.
2. If the complaint cannot be rectified, replace the door beltline trim bars, door upper trim bars and rear side window with trim element with optimized protective coating.

WIS-References

Document number	Title	Note
-----------------	-------	------

XENTRY TIPS

AR67.30-P-4000lws	Remove/install rear side window	Operation step 6.1
AR72.10-P-1905lw	Remove/install sealing for crank window on front door	
AR72.12-P-1911lw	Remove/install seal for crank window on rear door	

Symptoms

Body > Door/Flap > Door > Trim > Surface damage

Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC
A0009864674	11		Polish	1		X
A2056907107			ASSEMBLY TRIM STRIP LEFT	1	Valid for model 205.0/2 with code P15/P23/P31/P90	X
A2056907207			ASSEMBLY TRIM STRIP RIGHT	1	Valid for model 205.0/2 with code P15/P23/P31/P90	X
A2056907307			ASSEMBLY TRIM STRIP LEFT	1	Valid for model 205.0 with code P15/P23/P31/P90	X
A2056907407			ASSEMBLY TRIM STRIP RIGHT	1	Valid for model 205.0 with code P15/P23/P31/P90	X
A2056907507			ASSEMBLY TRIM STRIP LEFT	1	Valid for model 205.0/2 with code P55/P55+(P15/P31)/P60+P90/M016	X
A2056907607			ASSEMBLY TRIM STRIP RIGHT	1	Valid for model 205.0/2 with code P55/P55+(P15/P31)/P60+P90/M016	X
A2056907707			ASSEMBLY TRIM STRIP LEFT	1	Valid for model 205.0 with code P55/P55+(P15/P31)/P60+P90/M016	X
A2056907807			ASSEMBLY TRIM STRIP RIGHT	1	Valid for model 205.0 with code P55/P55+(P15/P31)/P60+P90/M016	X
A2056907907			ASSEMBLY TRIM STRIP LEFT	1	Valid for model 205.2 with code PP15/P23/P31/P90	X
A2056908007			ASSEMBLY TRIM STRIP RIGHT	1	Valid for model 205.2 with code PP15/P23/P31/P90	X
A2056908107			ASSEMBLY TRIM STRIP LEFT	1	Valid for model 205.2 with code P55/P55+(P15/P31)/P60+P90/M016	X
A2056908207			ASSEMBLY TRIM STRIP RIGHT	1	Valid for model 205.2 with code P55/P55+(P15/P31)/P60+P90/M016	X
A2057204333			ASSEMBLY SEALING RAIL OUTER LEFT	1	Valid for model 205.0/2	X
A2057204433			ASSEMBLY SEALING RAIL OUTER RIGHT	1	Valid for model 205.0/2	X
A2057204533			ASSEMBLY SEALING RAIL OUTER LEFT	1	Valid for model 205.0/2 with code P55/P60+P90/M016	X
A2057204633			ASSEMBLY SEALING RAIL OUTER RIGHT	1	Valid for model 205.0/2 with code P55/P60+P90/M016	X
A2057204933			ASSEMBLY SEALING RAIL OUTER LEFT	1	Valid for model 205.0/2	X

XENTRY TIPS

A2057205033		ASSEMBLY SEALING RAIL OUTER RIGHT	1	Valid for model 205.0/2	X
A2057205133		ASSEMBLY SEALING RAIL OUTER LEFT	1	Valid for model 205.0/2 with code P55/P60+P90/M016	X
A2057205233		ASSEMBLY SEALING RAIL OUTER RIGHT	1	Valid for model 205.0/2 with code P55/P60+P90/M016	X
A2057306306		ASSEMBLY SEALING RAIL OUTER LEFT	1	Valid for model 205.0 with code P15/ P23/P31/P90	X
A2057306406		ASSEMBLY SEALING RAIL OUTER RIGHT	1	Valid for model 205.0 with code P15/ P23/P31/P90	X
A2057306506		ASSEMBLY SEALING RAIL OUTER LEFT	1	Valid for model 205.0 with code P55/ P55+(P15/P31)/P60+P90/M016	X
A2057307106		ASSEMBLY SEALING RAIL OUTER LEFT	1	Valid for model 205.0 with code P76	X
A2057307206		ASSEMBLY SEALING RAIL OUTER RIGHT	1	Valid for model 205.0 with code P76	X

Operation numbers/damage codes

Op. no.	Operation text	Time	Damage code	Note
			67B1247	
			67P1247	
			72A4647	
			72N4647	
			73A4047	
			73N4047	
			72E0A47	
			72T0A47	
			73E0B47	
			73T0B47	
			67B1347	
			67P1347	