

Traffic light view intermittently inoperable after performing a software update of the MBUX Multimedia System (A26/17)

Topic number	LI82.85-P-075094
Version	2
Function group	82.85 - Navigation and Communication systems
Date	1/17/23
Validity	Model Series 206, 223, 232, and 297 with code U19
Reason for change	Software update available for the head unit as of E329.5 Added validity for 254, 295, 296

Complaint

Traffic Light View is intermittently inoperable after updating the MBUX Multimedia System (A26/17) to E316.5.

Cause

Previously available MBUX software release.

Remedy

A new software remedy is currently available. Please update the head unit software to version E329.5 or newer.

Note: Do not replace any parts for this complaint.

Symptoms				
Communication/information > Assistance and warning systems > Augmented reality camera > Malfunction				
Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note