

## Lower Multifunction Steering Wheel Button Group (A74/2) Display inoperable

---

Topic number	LI82.90-P-075727
Version	1
Function group	82.90 - On-board communications system, multifunction steering wheel, central control functions
Date	1/9/23
Validity	Model series 206, 232, 295 and 297 with code U88
Reason for change	

---

### Complaint

The display in the Lower Multifunction Steering Wheel Button Group (A74/2) may be completely or partially inoperable (see attached picture).

Note: There is no loss of vehicle functionality due to this complaint

Attachments	
File	Description
<a href="#">ASCM223 complaint.jpg</a>	complaint picture

### Cause

The complaint may occur when a new user profile is created in MBUX.

### Remedy

Immediate measure:

Perform a user data reset of the MBUX Multimedia System (settings -> system -> reset).

Long-term measure:

Updated AMG Drive Unit (N145/1) software is under development.

NOTE: Do not replace parts for this complaint

Symptoms
Overall vehicle > Power supply > Fuel cell > Malfunction
Operation numbers/damage codes

# XENTRY TIPS

---

Op. no.	Operation text	Time	Damage code	Note
			4601C52	Display fault ASCM223
			4601D52	Display fault ASCM223