A PDF of this newsletter and previous ones can be found by logging in to ServiceNet and clicking on the <u>Elsa</u> <u>Newsletter</u> section in the Technician References menu.



Audi Elsa Newsletter

Edition 89: June 9, 2014

Content

- <u>ElsaPro Software Update</u>
- <u>Technical Bulletins</u>
- Pending Service Solutions
- <u>Campaigns</u>
- <u>Updates</u>
- <u>Suggestions</u>



ElsaPro Software Update

The ElsaPro system application was updated on June 1. This update brought a couple changes that you should see and that will help improve the product for your use:

New: VIN column in Job Results List

When looking up existing jobs, a column for the VIN has been added to more easily identify the vehicle.

o results list 🙀					
Job number. *	Repair order	100	Model Code	Open campaignalactions	
57		WAUKJBFMXDA006817	4235NT	NO	
57.		TVW8N7A35CC036648	A322R1	YES	
66	6	1VW6N7A3XDC029874	51/21/14	YES	
67.	8	WVW0M7AJ8CW192551	5K129M	NO	
67	È.	WVWQU9AN9AE533616	357200	NO	
671	()	3VWJP7AT80M659316	501353	NO	
68		WAUCVAFD68N011070	4H25AA	NO	
68.		WV08V7AX38W521823	5N17V3	NO	
68	k.	WV2N847073H001750	7DCMA3	NO	
721			136		
73			94/2		
73	k.	2VW0x7AJ08M331347	162W\$3	NO	
74		3VW0X7AJ06M331347	142W53	NO	

Fixed: Technical Bulleting Search

The issue of "No results found" when searching for specific Technical Bulletin (TB) instance numbers or key words has been fixed. Users should now have no issue finding a particular TB applicable for a specific vehicle using the Search function. Back to top

Technical Bulletins

01 MIL on (DTC PO	13E00 - 02 ser response) (203	nsor bank 1 sensor 2, delayed 37307/1)	
Model(s)	Year	Vehicle Specific Equipment	
A4, A5, A5 Cabriolet	2013-2014	CAEB, CAED engines	
Allroad	2013	CAEB, CAED engines	
 MIL on. DTC P013E00 (02 Sensor Bank 1 Sensor 2 Delayed Response - Rich to Lean) is stored in the engine control module (ECM), J623 (address word 01). 			
Productio	n Solution: This	data is not available.	

		t move after stop due to simultaneous l accelerator pedals (2003658/6)
Model(s)	Year	Vehicle Specific Equipment
All	2000–2016 Not Applicable	
approxir	nately 1,400 RPM I/or the vehicle he	the engine returns to idle speed of although the accelerator is depressed, esitates (lacks power on take-off). DTCs are stored.
	Production Sol	ution: Not applicable.

00 A	udi engine oil-fill	ing procedure (2033576/2)
Model(s)	Year	Vehicle Specific Equipment
All	2008–2016	Not Applicable
	change service, a c level	amount of oil was added to the engine heck of the oil level shows that the oil is not okay. ution: Not applicable.

01 MIL on and/or oil pres (20	ssure warnin 033379/3)	ng on (DTC P164D00)
Model(s)	Year	Vehicle Specific Equipment
S4, S5, S5 Cabriolet, A6, A7, Q5, Q7	2013- 2014	3.0 FSI Engine
a) o DTC P164D00 (Oil	ddress word pressure swi malfunc essure warni	tch for reduced oil pressure tion) ng light may be on.

	Vehicle Specific Equipment
2012-2014	Xenon or LED Headlights
• Lower	ation is present in the headlight headlight lens cracking eadlight housing cracking
	 Heavy condens Lower

Pending Service Solutions

No Pending Service Solutions this week.

Campaigns

No new campaigns this week.

Updates

No new updates this week.

Suggestions

Please send comments or suggestions to: aoa.workshopinformation@audi.com

Back to top

© 2014 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.