

<b>Reference</b>	SSM71963
<b>Models</b>	F-TYPE / X152
<b>Title</b>	Front to rear power cable detachment from the through panel stud
<b>Category</b>	Electrical
<b>Last modified</b>	05-Sep-2014 00:00:00
<b>Symptom</b>	203000 Basic Electrical
<b>Attachments</b>	Doc11.pdf
<b>Content</b>	<p><u>Issue:</u> The front to rear power cable has become detached from the through panel stud, where it passes through the boot floor.</p> <p><u>Cause:</u> Failure of the friction weld between the cable and stud. (see file attached as an example).</p> <p><u>Action:</u> In order to effect a first time repair it will be necessary to replace the whole front to rear power cable assembly. There is no temporary repair or lower level assembly that is currently available.</p>