

<b>Reference</b>	SSM71995
<b>Models</b>	XK / X150
<b>Title</b>	XK Vehicles - Damaged Armrest Liner
<b>Category</b>	Body
<b>Last modified</b>	05-Nov-2014 00:00:00
<b>Symptom</b>	107000 Interior Trim
<b>Attachments</b>	11Liner damage - PIC 1.pdf 11Removal process - PIC 2.pdf

**Content**Issue:

Customers have reported that the Armrest liner is damaged – eg: Corner broken – See pic 1 as an example

Cause::

Poor initial fit / interference contact

Action:

If any damage is found on the armrest liner only, then replace the liner assembly, which is available as a separate part, having the service number C2C18467

**How to Repair**

1. With armrest fully forward raise vertically
2. Hold armrest in position and pull liner firmly from centre to release clips – See pic 2 as an example
3. Fit replacement liner and ensure that all 3 clips engage