

Body/Chassis – Water Leak From Roof Area

Customer Voice:

- A customer may complain that water is leaking into the vehicle cabin.

Technical Description:

- Water may enter the vehicle cabin through a roof body seam or gap in the panoramic roof opening panel cassette sealant.

Status:

- **SSM 75903** has been published to address a potential water leak path through the roof body seam.
- Roof water leaks should be able to be repaired without the need to remove the complete roof cassette assembly.

22-23MY Range Rover, 23MY Range Rover Sport SVR

