

<b>Reference</b>	SSM75925
<b>Models</b>	Defender / L663 Discovery / L462 New Range Rover / L460 New Range Rover Sport / L461 Range Rover / L405 Range Rover Sport / L494 Range Rover Velar / L560
<b>Title</b>	19MY Onwards - Oil Leak – Transmission Oil Cooler Pipes
<b>Category</b>	Driveline
<b>Last modified</b>	20-Jan-2023 00:00:00
<b>Symptom</b>	510000 Fluid Concerns
<b>Content</b>	<p><u>Issue:</u> JAGUAR LAND ROVER is investigating customer/technician reports of an oil leak. After investigation the leak is identified as coming from the Transmission oil cooler pipes.</p> <p><u>Cause:</u> Unknown at this time.</p> <p><u>Action:</u> Please carry out the following:</p> <ul style="list-style-type: none"> <li>-Confirm the vehicle symptoms as reported.</li> <li>-Before repairing, please take photographs of the current state before replacing any components.</li> <li>-Attach all the photographs to an ePQR, if you've rectified the customer symptom(s), quoting this SSM, along with the repair. Please hold onto the parts replaced, as per the warranty policy (30 days).</li> </ul> <p>Thank you in advance for your assistance with this matter.</p>

anBhdHRicnM7MjAyMy0wMS0yMFOxMj01Nj01MC4xMjRaOzEzN4yMjYhNzluMTl3Ow==