

Service Bulletin

Bulletin No.: 21-NA-091

Date: February, 2023


INFORMATION


Subject: Information on Normal Camera Display Operation - Flashing Diamond - Spot - or UFO like Image on Camera Display


This bulletin replaces PIT5799A. Please discard PIT5799A.

Brand:	Model:	Model Year:		VIN:		Funina	T
		from	to	from	to	Engine:	Transmission:
Cadillac	CT4	2020	2020				
	CT5		2021				
	Escalade						
	Escalade ESV						
	XT4		2023				
Chevrolet	Bolt EV	2020	2020				
	Corvette		2021				
	Silverado 1500						
	Silverado 2500HD/ 3500HD		2022				
	Tahoe		2021				
	Suburban						
GMC	Sierra 1500	2020	2021				
	Sierra 2500HD/ 3500HD		2022				
	Yukon		2021				
	Yukon XL						

Involved Region or Country	North America, Brazil, Chile, Colombia, Ecuador, Paraguay, Peru, Europe, Uzbekistan, Middle East, Israel, Palestine, Japan, GM Korea Company, Cadillac Korea (South Korea), Australia/New Zealand			
Additional Options (RPOs)	Equipped with UVI, UVS, UV2, or UVA			
Condition	Some customers may comment on a flashing light present on the radio display with the camera on, usually is corrected by an ignition cycle.			







Version	4
Modified	Released April 13, 2021
	Revised May 03, 2021 – Added the Cadillac XT4 and updated the Involved Region or Country section.
	Revised November 17, 2021 – Added the 2022 Model Year to the Silverado 2500HD/ 3500HD and Sierra 2500HD/3500HD models.
	Revised January 30, 2023 – Removed Rearview from Subject, added the 2022–2023 Model Year to Cadillac XT4, updated the Involved Region or Country section, added UVA to Additional Options (RPOs) section, revised Condition and Correction sections.