Technical Service Bulletin



90 Instrument Cluster: telephone tab is shown after the vehicle was parked showing the navigation tab 90 23 07 2069510/1 February 14, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3	2022 – 2023	All	Not Applicable

Condition

Customer states:

The vehicle was parked showing the navigation tab on the instrument cluster display.

After coming back to the vehicle and turning on the ignition, the phone tab is shown occasionally.

The customer would expect the previously shown tab to be displayed.

Workshop findings:

No relevant DTCs are stored.

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

No repair is available at this time.

- 1. Do not perform any repairs. Any repairs for this concern may be denied.
- 2. Instruct the customer that this condition is normal.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

Page 1 of 2

© 2023 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Technical Service Bulletin



All part and service references provided in this TSB (2069510) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.