



Service Bulletin

Bulletin No.: 17-NA-078

Date: February, 2023

INFORMATION

Subject: Information on Corvette and Camaro Exhaust Tone During Wide Open Throttle While in Sport or Track Modes

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2015	2023	—		6.2L, 5.5L (RPOs LT1, LT2 Equipped with NPP, LT4, LT5 or LT6)	All
	Corvette	2015	2023				

Involved Region or Country	North America, Europe, Japan, Middle East
Condition	Some customers may comment that they hear a "pop" or "backfire" sound from the exhaust while performing a wide open throttle maneuver while in Sport or Track driving modes.
Cause	The exhaust sound heard during the wide open throttle maneuver is normal.
Correction	No repairs should be performed if there are no diagnostic codes, and the exhaust sound that the customer noticed goes away when the driver mode is selected to any other driver mode other than Sport or Track. Note: The C8 Generation Corvettes may experience the exhaust sound mentioned in the bulletin when the following driving modes are selected; Sport, Track, MY Mode and Z Mode depending on the personalization of the engine sound.

Parts Information

No parts are needed for this concern.

Customer Information

Please communicate to the customer this condition is a normal characteristic of their vehicle. It will not impact the designed performance or reliability of the vehicle.

Please share this information with the customer, including a copy of this bulletin.

Version	5
Modified	Revised November 2, 2018 – Added the 2018 and 2019 Model Years and the LT1 and LT5 engine RPOs. Revised September 18, 2020 – Added the 2020 Chevrolet Corvette, 2020-2021 Chevrolet Camaro, updated the Engine column, updated the Involved Region or Country section and added a Note to the Correction. Revised July 29, 2022 – Updated the Model Years to 2023. Revised February 15, 2023 – Added the 5.5L (RPO LT6) engine and updated the Note in Correction.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION