

SERVICE ACTION CAMPAIGN H427 BLANKING PLUG OIL LEAK

OWNER NOTIFED SERVICE ACTION H427 – BLANKING PLUG OIL LEAK

AFFECTED MODELS	21-22MY F-PACE
VOLUME AFFECTED	US 2202 CAN 336
REPAIR	On certain 2021 and 2022 model year Jaguar F-PACE vehicles, the cylinder block vacuum pipe blanking plug may become detached, resulting in an engine oil leak and stress on crank case breather system. A replacement of the blanking plug is required.
REPAIR TIME	2.3 hrs + DIDO
CAMPAIGN LAUNCH	February 6th, 2023
Notes	Retailers should check the warranty portal to confirm affected VIN and following the service procedure, repair all affected unsold vehicles before sale and delivery. Customer vehicles should be repaired at the next service visit. All customers will be notified by mail and asked to contact their retailer for a service appointment.