# **Technical Service Bulletin**



#### 48 DTC U13D500/C135DF1 stored in J500

48 23 38 2069614/1 March 7, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
e-tron GT, and RS e-tron GT	2022 – 2023	All	Not Applicable	

### Condition

#### **Customer states:**

The instrument cluster message "Lane departure warning fault" appears when the vehicle is started.

#### **Workshop findings:**

The following DTCs are stored in the steering control unit J500 (address 0044):

- U13D500 Function restriction, directional stabilization assistance (Symptom code 15872).
- C135DF1 Power steering control module does not implement request (Symptom code 17920).

## **Technical Background**

Not Applicable

### **Production Solution**

Not Applicable

### **Service**

If only the DTCs described above are stored in address 0044, <u>do not</u> perform any repair work. Clear DTCs and release the vehicle, the DTC is unlikely to occur again..



The replacement of parts does not solve this issue. Claims for replaced parts will be subject to review.

## Warranty

Claim Type • 110 up to 48 Months/50,000 Miles.
--

#### Page 1 of 2

#### © 2023 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

# **Technical Service Bulletin**



	<ul> <li>G10 for CPO Covered Vehicles – Verify Owner.</li> <li>If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li> </ul>				
Service Number:	4835				
Damage Code:	0040				
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 40 TU)		
	Road test prior to the service procedure	No allowance	0 TU		
	Road test after the service procedure	No allowance	0 TU		
Claim Comment:	As per TSB 2069614/1				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

#### **Additional Information**

All part and service references provided in this TSB (**2069614**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.