



Preliminary Information

PIT5732C Information on DEF Tank Relocation

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 3500HD Chassis Cab	2020 - 2023	All	All	L5P	All
GMC	Sierra 3500HD Chassis Cab	2020 - 2023	All	All	L5P	All

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Involved Region or Country	North America
Additional Options (RPO)	N2L Single Rear Fuel Tank
Condition	A Dealer or Upfitter may be looking for information on relocating the DEF tank to install a service body.
Cause	Information not readily available in Service Information (SI.)

Correction:

Reference the latest version of GM Upfitter Integration Bulletin 156. The information can be found at <http://www.gmupfitter.com/> under the "Technical Bulletin" Tab and then "Show all bulletins."

Version History

Version	4
Modified	02/13/2020 - Created on 02/12/2021 - Added 2021 Model Year 02/09/2022 - Added 2022 Model Year 02/27/2023 - Added 2023 Model Year



GENERAL MOTORS