

SERVICE ACTION CAMPAIGNS

| OWNER NOTIFIED SERVICE ACTION N766 H427 – BLANKING PLUG OIL LEAK | |
|------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| AFFECTED MODELS | 21MY Range Rover Velar 21-22MY F-PACE |
| VOLUME AFFECTED | JAG US 2202 CAN 336 LR US 1675 CAN 588 |
| REPAIR | On certain vehicles, the cylinder block vacuum pipe blanking plug may become detached, resulting in an engine oil leak and stress on crank case breather system. A replacement of the blanking plug is required. |
| REPAIR TIME | 2.3 hrs + DIDO |
| CAMPAIGN LAUNCH | Jaguar - February 6th, 2023 Land Rover – February 22nd, 2023 |
| Notes | Retailers should check the warranty portal to confirm affected VIN and following the service procedure, repair all affected unsold vehicles before sale and delivery. Customer vehicles should be repaired at the next service visit. All customers will be notified by mail and asked to contact their retailer for a service appointment. |

| CUSTOMER SATISFACTION PROGRAM N765 – INCORRECT EMISSIONS LABEL INSTALLED | |
|--------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| AFFECTED MODELS | 22MY and 23MY Range Rover 23MY Range Rover Sport |
| VOLUME AFFECTED | US 81 |
| REPAIR | On certain Range Rover and Range Rover Sport vehicles, the Vehicle Emissions Control Information label wrongly states the code SCE. Retailers are to install the correct emissions labels on affected vehicles. |
| REPAIR TIME | 0.3 hrs + DIDO |
| CAMPAIGN LAUNCH | February 21st, 2023 |
| Notes | Retailers should check the warranty portal to confirm affected VIN and following the bulletin service procedure, inspect/repair all affected vehicles at the next service visit. |