

## POWERTRAIN – ENGINE PRIMARY BELT SHREDDING - P6-3.0L(MHEV)

---

### Customer Voice:

- Jaguar Land Rover (JLR) is investigating retailer reports of P6 MHEV gasoline engines with primary drive belt failures. (Shredding failure)

### Technical Description:

- Pulleys and brackets are to be inspected for and damage or alignment issues

### Status:

- Please raise an TA with the following information.
  - Pictures of any damaged components
  - Condition of all pulleys BiSG, Idler, Crank, and A/C

Refer to SSM 75953 / SSM 75954

19-23MY Land Rover Defender,  
Discovery, Range Rover, RR Sport, RR  
Velar  
19-23MY Jaguar XE, F-PACE

