



Technical Service Bulletin

Technical Service Bulletin:
TSB230059

Released Date: 21-Mar-2023

Vibration Incidents on Navistar®, International® Truck, or IC™ Bus Chassis

Vibration Incidents on Navistar®, International® Truck, or IC™ Bus Chassis

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

Engines:

- B6.7 CM2350 B121B
- B6.7 CM2450 B155B
- L9 CM2350 L116B
- L9 CM2350 L123B
- L9 CM2450 L126B
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2350 X117B
- X15 CM2450 X124B
- X15 CM2450 X134B

Original Equipment Manufacturers:

- Navistar® International® truck
- IC™ bus since 2017.

Issue Summary

Symptom:

- Vibration

Root Cause:

- Vibration is **not** typically caused by the engine

Resolution

Re-direct incident to Navistar® first by opening a case file in their system about this issue.

Service Instructions

Navistar® recommends opening a case file in their system to start troubleshooting any vibration issues first and once data is collected, Navistar® will escalate to Cummins Inc. if needed.

Document History

Date	Details
2023-3-17	Module Created

Last Modified: 21-Mar-2023
