

Subject: Engineering Information - Fuel Smell and/or Fuel Leaking From Fuel Rail Pressure Sensor

This PI has been revised to end the need for gathering information from the field. Please discard PIE0722A.

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2022	2023	—	—	Equipped with 3.6L (RPO LFY)	—
Chevrolet	Traverse						

If you encounter a vehicle with the above condition, refer to PIP5915 for further diagnosis.

Version	3
Modified	Released October 21, 2022 Revised February 02, 2023 - Updated steps 2 and 3 under the Correction. Revised March 29, 2023 - Ended the need for gathering further information from the field.