



Technical Journal

TITLE:

Info request, loose door sealing strips

REF NO: TJ 34071.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2018-09-04	STATUS DATE: 2018-09-11
FUNC GROUP: 8451	FUNC DESC: Sealing moulding for side door	Page 1 of 3	

“Right first time in Time”

Attachment

File Name	File Size
TJ34071.jpg	0.1326 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
225							2019-2019		0000315-9999999	201817-999952
235							2018-2019		0051346-9999999	201746-999952
236							2018-2019		0027394-9999999	201746-999952
238							2018-2019		0028833-9999999	201746-999952
246							2018-2019		0042850-9999999	201746-999952
256							2018-2019		0344889-9999999	201746-999952
536							2019-2019		0000329-9999999	201746-999952

CSC Customer Symptom Codes

Code	Description
M3	Exterior trim/components/Moldings, trim loose
ZP	Sealings doors, windows, lids/Loose, poor fit, warped
R1	Doors/Water leakage/Front side door
R2	Doors/Water leakage/Rear side door



VST Operation Number

VST Operation Number	Description
84532-2	Weatherstrip side door front replace
84533-2	Weatherstrip side door rear replace

DTC Diagnostic Trouble Codes

Text

DESCRIPTION:

If any front or rear door sealing strips are loose.

Submit a Vehicle Report for information with detailed photos showing the failure (overview + close-up).

Include what door is affected and the failure area, see attachment.


SERVICE:

Replace the sealing strip according to VIDA.

VEHICLE REPORT:

Yes, please submit a Vehicle Report with detailed photos showing the failure. Add the nr of the failure area and what door that is affected according to attachment. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8451.

To view TJ attachment continue to next page. This TJ has one attachment.



TJ 34071