

34-096 - 579 Radar Resistor

4/13/2023

 [Edit](#)  [Clone](#)

34-096

34-096 - 579 Radar Resistor

Subject

34-096 - 579 Radar Harness

Whats New Abstract

Fix As Fail – All New Model 579 chassis with Bendix radar option may have a harness rub against the radiator that is causing possible damage.

Condition

The Bendix radar wiring harness needs to be wrapped and re-secured if it is rubbing against the radiator.

Chassis Affected

New Model 579 chassis manufactured with the Wabco or Bendix radar option manufactured through 03/20/2023.

Action

Fix-As-Fail

If a customer comes into your dealership and demonstrates the condition above, wrap the specified wiring harness and re-secure per the procedure provided.

Warranty

Through Standard Warranty or any applicable active Extended Warranty, Peterbilt will pay for parts and labor:

- 0.3 hours labor to wrap the specified wiring harness and re-secure per the provided procedure.
Use Quick Claim code **34096A** for claims under Standard Warranty 12 months / 100,000 miles.
Use Quick Claim code **34096B** for claims under Extended Warranty (any Warranty agreement beyond 12

months / 100,000 miles).

PRWS CLAIM CODING			
Campaign Code:	34096	Campaign Type	Field Repair
Claim Category:	Truck	Repair Type	Fix-As-Fail
Customer Concern Code	042	Causal Code	49
Corrective Action Code	13	Responsibility Code:	VEHSTD
Failure Location	034-004-094	Causal Part	A92-6181
Supplier Code	N/A	SRT Code	B34-096 0.3 hrs. labor for: Wrap radar harness per bulletin procedure.

Parts

Source parts locally.

Quantity	Part Number	Description
1	Source locally	Coroplast wrap (tape roll)
2	Source locally	Cable ties

Procedure

Please follow your dealership's safety procedures and precautions to ensure the vehicle can be safely repaired and maintained.

Please see the repair procedure in the Links section of this bulletin.

Attachments

[34-096 Repair Procedure](#)

Authored by D. Cook