



Bulletin No.: PIT5998

Published date: N/A

Preliminary Information

PIT5998 Diagnostic Tip- Steering Wheel Shake After Hitting Bump(s)

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Envision	2019 - 2020	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment on a continued shaking from the steering after hitting a bump or series of bumps.
Cause	Front control arm rear hydraulic bushings leaking oil.



Correction: Inspect the front control arm rear bushings for evidence of oil leaking. If evidence of a leak is found replace the affected control arm.

Version History

Version	1
Modified	04/05/2023- Created on



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.