<b>TOYOTA</b>	Tech Tip T-TT-0	730-23	April 05, 202
MIL ON and Multiple	DTC for MGR	Communication	Market USA
Codes			
Service Category		Section	
Drivetrain		Hybrid Transmission/Transaxle	
Applicability			

## **APPLICABLE VEHICLES**

2023MY Crown Platinum

2023	Crown

## **CONDITION**

Vehicle may exhibit one or all in combination of the following DTC U115687 or U11B900 or U11B987 or U11BF87 shortly after short pin installed during PDS/PDI.

## **RECOMMENDATIONS**

If you have cleared the codes and the codes have returned with the vehicle odometer over 13 miles and has over 12hrs since short pin installed, please contact TAS. Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or a holiday, continue with diagnosis and repair. Please save all details and contact TAS on the next available workday.

## **LINK REFERENCES**

This Tech Tip does not contain any link references

Expires on 07/05/2023