

Technical Service Bulletin



94 How to properly document optical concerns for headlights and tail lights

94 23 63 2061922/2 May 8, 2023. Supersedes Technical Service Bulletin Group 94 number 21-33 dated February 4, 2021, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All Audi Models	2010 – 2024	All	Not Applicable

Condition

Revision	Date	Purpose
2	-	Revised header (Added Model Years 23 and 24) Revised <i>Technical Background</i> (Modified verbiage)
1	2/4/2021	Initial publication

Customer states:

There is a visual concern or defect present with the headlight(s) or taillight(s).

Technical Background

For visual concerns related to a headlight or taillight submitted under warranty, we ask that defect flags and photos be used to identify and document the visual concern or defect. Photos should be uploaded to DOC-IT in case they are needed during the review.



Note:

Defect flags can be found in the attachment tab of this TSB. These can be printed and used as needed.

Production Solution

Not Applicable

Service

1. Before any repairs are made or components are removed, please fill out the defect flag and take photos as shown below.
2. When returning headlights or tail lights to the WPRC, use the new part packaging and take necessary precautions to avoid damage during shipping.



3. When to use the defect flags and photo documentation:

- Moisture buildup (please see associated TSBs below before proceeding).
- Foreign objects or loose components inside the lamp.
- Haze, pitting, cracking, bubbles, or markings on the inside of the lens.
- If the concern is **NOT** related to outside influence and a warranty claim is submitted.

4. Three (3) photos are needed for the lamp to be replaced:

- 1 perspective view – showing the general area and identifies which lamp is affected.
- 1 close-up – clearly focused and showing the customer concern.
- 1 production label – shows the entire production sticker or label.



Note:

If another TSB is applicable as seen in the two examples below, please follow all other primary TSBs **before proceeding**:

- TSB 2012749: *94 Exterior lights, moisture accumulation* (All models).
- TSB 2058420: *94 Tail light or front indicator in bumper is cracked, broken, leaks, or does not work* (Q3, Q5, Q7, Q8, Audi e-tron quattro, and Audi e-tron Sportback).

Perspective photo:

- Entire area is visible in the photo which clearly identifies the lamp affected (figures 1 – 2).
- Photo is taken with the fault component still installed on the vehicle before components are removed.
- Photo is in focus and properly lit.
- Defect flag should be completely visible and legible.

The first photo should show a full picture of the affected component and the affected area of the cause should be marked with an arrow. This is for guidance.



Figure 1. Example of a perspective view photo.

Figure 2. Example of a headlight perspective view photo.



Figure 5. Example of tail light assembly label.



Figure 6. Example of headlight label.

Warranty



Note:

This TSB is only applicable when submitting a warranty claim for visual concerns on headlights and tail lights within NVLW or CPO Warranty. Please submit a separate claim for each affected headlight or taillight.

Use the following service numbers (PID) and damage codes according to the listed concerns:

9415/0030:

- For optical concerns on the inner headlight (e.g. foreign body, broken inner covers).

9419/0015:

- For cracks, scratches, or similar on the outer or inner lens of the headlight.

9431/0030:

- For optical concerns on the inner tail light assembly (e.g. foreign body).

9432/0015:

For cracks, scratches, or similar on the outer or inner lens of the tail light assembly.

Additional Information

The following Technical Service Bulletin(s) will be necessary to complete this procedure:



- TSB 2012749, *94 Exterior lights, moisture accumulation.*
- TSB 2058420, *94 Tail light or front indicator in bumper is cracked, broken, leaks, or does not work.*

All part and service references provided in this TSB (**2061922**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.