

Technical Service Bulletin



90 PSS Instrument cluster status field in driver information system is empty

90 23 26 2070448/1 May 22, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, RS 5, RS 5 Sportback, and Q5 e quattro	2022 – 2023	All	Analog Instrument Cluster

Condition

This bulletin applies to A5/S5, and Q5 e quattro Model Years 2022-2023.

In the driver information system on the instrument cluster, content is not shown for any of the tabs (Vehicle functions, Driver messages, Radio, Media, Phone, Navigation); this issue occurs very sporadically. The area affected when the issue occurs is marked as shown (Figure 1).



Figure 1: Driver information system is blank.



Note: The concern is resolved after a bus sleep cycle. To perform a sleep bus cycle, turn off the ignition, lock the vehicle, and let the vehicle sit undisturbed for 10 minutes, then turn the ignition back on and check the condition again.

Technical Background



Software issue in the instrument cluster.

Production Solution

Change of supplier for model year 2024.

Service

Explain to the customer that a solution is expected to be available by the end of the 3rd quarter of 2023 (subject to change) and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.

Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links* >> *Service*).

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All part and service references provided in this TSB (**2070448**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.