

**Volvo Car USA LLC****Technical Journal**

Technical Journal Title Vibration/shudder while braking		Ref. No. TJ 36202.2.0	
Issuer (Dept.) Technical Service		Issue Date 4/25/23	Status Date 4/28/23
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 5115	
Function Description Brake pad; brake pad kit		Page Page 1 of 2	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

If the customer experiences vibration/shudder while braking, please follow advice under Service. (This symptom may be felt in the steering wheel / brake pedal / car body / seats.)

CSC Customer Symptom Codes

Code	Description
V4	Brakes/Vibration/shudder/While braking

DTC Diagnostic Trouble Codes**Vehicle Type**

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2019-2023		-	201835-202318
225							2019-2023		-	201817-202318
227							2019-2023		-	201846-202318
234							2017-2017		-	201617-202318
235							2017-2023		-	201624-202318
236							2017-2023		-	201646-202318
238							2018-2023		-	201646-202318
246							2018-2023		-	201717-202318
256							2016-2023		-	201505-202318

SERVICE:

If the symptom is confirmed, proceed with replacement of the front brake pads according to VIDA.

Warranty claim info:

To get warranty claim accepted for the labor part described in this TJ, please use following data:

Failing Part : Front brake pad.

VST OP number: 51125.

Note that the TJ number must be stated in repair order text!

VST Operation Number

VST Operation Number	Description
51125	Brake pads, front

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 5115.