

Field campaign

Topic	Rear doors (left and right) - power close operational check during PDI (SC23/14)
Market area	Australia E04 Bentley rest Asia and Australia (6E04),China 796 VW Import Comp. Ltd (Vico), Beijing (6796),Germany E02 Bentley rest Europe (6E02),Japan E03 Bentley Japan (6E03),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2070402/1
Campaign number	EC79
Note	
Type	
US code	

Vehicle data

Bentayga extended wheel base

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
ZV1*	2023	E		*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
SJA	*	*	*	P	*	017138	020730		

Documents

Document name
master.xml
sc2314vinlist.pdf

Notes



Technical background

The operation of the left and right rear door power close operation is required to be checked during PDI

Remedy

Conduct the instructions within the Work section to completion

Customer notification

Please ensure the instructions within this procedure are conducted at the nearest opportunity, make a note of the required action on the workshop order before it is signed by the customer

If it is omitted to perform the work required during a workshop visit, the customer should be notified immediately

You should also pass on this information to your new and used car sales departments so that affected vehicles are checked and repaired immediately

Warranty accounting instructions

Warranty type 790

Damage service number EC79

Damage code 00 66

Criterion ID 01

Time to conduct the initial checks within the Work section (Not including the instructions within TPI 2069592/-

Labour operation code 58 51 02 50 (Use 99 index until 29/06/23)

Time 10 Time units

Time to conduct the rework instructions from TPI 2069592/-

Time to conduct steps 3 - 5 (x1) door

Labour Operation Code 58 25 15 00

Time 10 TU

Time to conduct steps 3 - 5 (x2) doors

Labour Operation Code 58 25 16 00

Time 20 TU

Time to conduct steps 6 - 7 (x1) door

Labour Operation Code 58 64 41 00

Time 10 TU

Time to conduct steps 6 - 7 (x2) doors

Labour Operation Code 58 64 41 01

Time 20 TU

Time to conduct Steps 8 - 10 (x2) doors

Labour Operation Code 58 64 01 00

Time 20 TU

Genuine parts

Not applicable

Parts supply

Not applicable

Parts despatch control

Not applicable

Technical background

The operation of the left and right rear door power close operation is required to be checked during PDI

Check

If the vehicle is not already listed as repaired in "Repair history" (in Elsa pro), check for the presence of the red paint completion mark as shown within the Identification section

If neither are evident please conduct the instructions within the Work section to completion

Genuine parts

Not applicable

Work

1) A battery test must have been conducted before proceeding NOTE: This must be conducted and claimed as part of the PDI procedure

2) Connect a suitable battery charger to the vehicle - Refer to Rep.Gr 27

- Switch on the ignition

NOTICE

A battery test must have been conducted before proceeding NOTE: This must be conducted and claimed as part of the PDI procedure

Left hand rear door (LHR)

3) Open the LHR door

- Sit on the LHR seat *HINT: Ensure a suitable cover is used to protect the seat*

CAUTION

The operative must ensure the following before conducting

- The RHF - LHF and RHR doors must all be closed
- The tailgate must be closed
- All windows must be closed

4) Referring to Figure 1 - Press and hold the left DOOR CLOSE button




Figure 1

- Check the LHR door fully closes/latches without the requirement to press the button a second time

CAUTION

During the failure mode the door actually moves to the first latching point only, the power latch does not activate which leaves the door in semi latched/closed state (not fully closed/latched)

- Once fully closed/latched - Fully reopen the LHR door
- Repeat the power close operation (x4) times (x5 in total)

NOTICE

In the event the door close/latch operation fails at any point the operative must conduct the instructions within TPI 2069592/-

However

In the event there are no power door close/latch operational issues and the power door could be power closed x5 times without any issues the operative must conduct the remaining instructions to completion

Right hand rear door (RHR)

5) Open the RHR door

- Sit on the RHR seat *HINT: Ensure a suitable cover is used to protect the seat*

CAUTION

The operative must ensure the following before conducting

- The RHF - LHF and LHR doors must be closed
- The tailgate must be closed
- All windows must be closed

6) Referring to Figure 1 - Press and hold the right DOOR CLOSE button

CAUTION

During the failure mode the door actually moves to the first latching point only, the power latch does not activate which leaves the door in semi latched/closed state (not fully closed/latched)

- Check the RHR door fully closes/latches without the requirement to press the button a second time
- Once closed/latched - Fully reopen the RHR door
- Repeat the power close operation (x4) times (x5 in total)

NOTICE

In the event the door close/latch operation fails at any point the operative must conduct the instructions within TPI 2069592/-

However

In the event there are no power door close/latch operational issues and the power door could be power closed x5 times without any issues the operative must conduct the remaining instructions to completion

7) A short road test should now be conducted to confirm no wind noise is evident NOTE: This must be conducted and claimed as part of the PDI procedure

8) Apply a red paint completion mark on the underside of the right hand rear door arrestor bracket (Figure 2)

Identification

Red paint completion mark on the underside of the right hand rear door arrestor bracket (Figure 2)



Figure 2

▲ [Repair instructions](#) ▲ [Notes](#)

INTERNAL

SJAHT2ZV4PC017138	SJAHY14V3PC018235	SJAHT2ZV8PC018681	SJAHY14V8PC019090	SJAHY14V5PC019449
SJAHT2ZV2PC017347	SJAHY14V6PC018245	SJAHY14V5PC018687	SJAH514V0PC019092	SJAHY14V7PC019453
SJAHT2ZV1PC017422	SJAHY14VXPC018250	SJAHY14V4PC018695	SJAHY14V8PC019106	SJAHT2ZV8PC019457
SJAHT2ZV4PC017611	SJAHY14V5PC018270	SJAH514VXPC018709	SJAHY14VXPC019107	SJAHL1ZV6PC019466
SJAHY14V6PC017631	SJAHY14V4PC018275	SJAHY14VXPC018717	SJAHY14V3PC019109	SJAHY14V6PC019489
SJAHY14V1PC017648	SJAHY14V1PC018301	SJAHT2ZV6PC018730	SJAHY14V4PC019118	SJAHY14V4PC019491
SJAH514V2PC017652	SJAHY14V7PC018304	SJAHY14V6PC018732	SJAHY14V7PC019128	SJAHT2ZV9PC019497
SJAHY14V7PC017654	SJAHY14V6PC018312	SJAHT24V1PC018738	SJAHY14V1PC019142	SJAHT2ZV5PC019500
SJAH514V9PC017681	SJAH514V1PC018324	SJAHT2ZV5PC018752	SJAHY14V7PC019145	SJAHY14V7PC019503
SJAH514V6PC017718	SJAHY14V8PC018327	SJAHY14V5PC018754	SJAHT2ZV4PC019147	SJAHT2ZV8PC019507
SJAHY14V3PC017750	SJAHT2ZV8PC018339	SJAHY14V4PC018759	SJAHY14V2PC019148	SJAHY14V1PC019514
SJAHY14V6PC017757	SJAHT2ZV9PC018348	SJAH514V4PC018771	SJAHY14V8PC019154	SJAHT2ZV0PC019520
SJAHT2ZVXPC017760	SJAHY14V2PC018355	SJAHT2ZV4PC018774	SJAHL14V5PC019157	SJAH514VXPC019522
SJAHY14V0PC017771	SJAHT2ZV1PC018358	SJAHT2ZV8PC018776	SJAHY14V5PC019158	SJAHT2ZV3PC019530
SJAHY14V3PC017778	SJAHY14V1PC018363	SJAHY14V9PC018790	SJAHY14V3PC019160	SJAHL1ZVXPC019535
SJAHY14V4PC017787	SJAHY14V7PC018366	SJAHY14V9PC018806	SJAHY14V4PC019166	SJAHT2ZV4PC019536
SJAHY14VXPC017793	SJAHT2ZV6PC018372	SJAHY14V6PC018813	SJAH514V0PC019173	SJAH514V7PC019543
SJAHY14V5PC017796	SJAHT2ZV9PC018379	SJAHT2ZV1PC018828	SJAHY14V3PC019174	SJAHL1ZV4PC019546
SJAHY14V7PC017847	SJAHY14V8PC018392	SJAHT2ZV5PC018833	SJAHY14V9PC019177	SJAHT2ZV8PC019555
SJAH514VXPC017852	SJAHY14V9PC018403	SJAHY14V4PC018843	SJAHY14V0PC019178	SJAHY14V6PC019556
SJAHY14V5PC017863	SJAHT2ZVXPC018407	SJAHY14V5PC018852	SJAHY14V9PC019180	SJAHL1ZV8PC019582
SJAHY14V6PC017869	SJAHT2ZV1PC018411	SJAHY14V9PC018854	SJAHT2ZV4PC019181	SJAH514V1PC019585
SJAHY14V7PC017881	SJAH514V1PC018422	SJAHY14V7PC018870	SJAHY14V4PC019183	SJAHL1ZV7PC019590
SJAHY14V4PC017904	SJAHY14V3PC018428	SJAHY14V2PC018873	SJAH514V2PC019188	SJAHY14V1PC019593
SJAHT2ZV5PC017908	SJAHT2ZV7PC018431	SJAHY14V6PC018875	SJAHY14V5PC019192	SJAHY14V7PC019596
SJAHY14V0PC017916	SJAHT2ZV9PC018446	SJAHY14V7PC018884	SJAHY14V0PC019195	SJAH514V6PC019601
SJAHT2ZVXPC017922	SJAHT2ZV7PC018459	SJAHT2ZV6PC018887	SJAHY14V2PC019196	SJAHL1ZV7PC019606
SJAHY14V1PC017925	SJAH514V5PC018469	SJAHY14V4PC018888	SJAHT2ZV6PC019201	SJAHT2ZV1PC019624
SJAHY14V4PC017952	SJAHT2ZV8PC018471	SJAHY14V2PC018890	SJAHY14V8PC019204	SJAHY14V5PC019628
SJAHY14VXPC017969	SJAHY14V6PC018486	SJAHY14V6PC018892	SJAHY14V3PC019210	SJAHT2ZVXPC019637
SJAHY14V0PC017981	SJAHY14VXPC018488	SJAH514V9PC018894	SJAHY14V9PC019213	SJAHY14V8PC019638
SJAHY14V1PC017987	SJAHY14V9PC018496	SJAHY14V9PC018899	SJAHY14V0PC019214	SJAHY14V8PC019641
SJAHY14V8PC017999	SJAHY14V9PC018501	SJAHT2ZV6PC018906	SJAHY14V4PC019216	SJAHY14V7PC019646
SJAH514VXPC018001	SJAHY14V2PC018503	SJAHY14V6PC018911	SJAHY14VXPC019222	SJAHT2ZV7PC019661
SJAHY14V7PC018027	SJAHY14VXPC018507	SJAHY14V8PC018912	SJAHT2ZV7PC019224	SJAHY14V0PC019665
SJAHY14V0PC018032	SJAHY14V7PC018514	SJAHY14V3PC018915	SJAHY14V5PC019225	SJAHY14V4PC019670
SJAHY14V2PC018033	SJAHT2ZV6PC018517	SJAH514V8PC018921	SJAH514V0PC019237	SJAHT2ZV2PC019681
SJAHY14VXPC018040	SJAHY14V9PC018529	SJAH514V9PC018927	SJAHY14V6PC019248	SJAHT2ZV8PC019684
SJAHY14V6PC018052	SJAHY14V9PC018532	SJAH514V4PC018933	SJAHY14V7PC019260	SJAHY14V6PC019699
SJAHY14V9PC018059	SJAHY14V2PC018534	SJAHT2ZV6PC018937	SJAHT2ZV7PC019269	SJAHY14V2PC019702
SJAHY14V9PC018062	SJAHT2ZV3PC018538	SJAHT2ZVXPC018942	SJAHY14V0PC019276	SJAHT2ZV3PC019706
SJAHY14V8PC018067	SJAHT2ZV3PC018541	SJAHY14V9PC018949	SJAHY14V6PC019296	SJAHT2ZV9PC019712
SJAHY14V0PC018077	SJAHY14V0PC018550	SJAHY14V0PC018953	SJAHY14V1PC019304	SJAHK14V9PC019729
SJAHY14V2PC018081	SJAHY14V9PC018580	SJAHT2ZV5PC018962	SJAHY14V0PC019309	SJAH514VXPC019732
SJAHY14V1PC018086	SJAHY14V2PC018582	SJAHY14V2PC018971	SJAHY14V1PC019318	SJAHY14V1PC019738
SJAHY14V5PC018088	SJAHY14V1PC018587	SJAHT2ZV3PC018975	SJAHY14V6PC019329	SJAHT2ZV7PC019739
SJAHY14VXPC018104	SJAHY14V4PC018597	SJAHY14VXPC018992	SJAHY14V1PC019335	SJAHY14V1PC019741
SJAHY14V5PC018107	SJAHY14V0PC018600	SJAHY14V5PC018995	SJAHY14V0PC019343	SJAHT2ZV6PC019747
SJAHY14V9PC018112	SJAHY14V7PC018609	SJAHY14V2PC019019	SJAHY14V2PC019344	SJAHT2ZVXPC019749
SJAHY14V0PC018113	SJAHY14V5PC018611	SJAHY14VXPC019026	SJAHY14V8PC019347	SJAHY14V2PC019750
SJAHY14V5PC018124	SJAHT2ZVXPC018620	SJAHY14V3PC019028	SJAHT2ZV2PC019356	SJAHY14V3PC019756
SJAHY14V4PC018132	SJAHY14V7PC018626	SJAH514V1PC019036	SJAHY14V4PC019362	SJAH514V8PC019759
SJAHT2ZV1PC018165	SJAH514V1PC018629	SJAHT2ZV5PC019044	SJAHY14VXPC019365	SJAHY14VXPC019771
SJAHT2ZV5PC018167	SJAHT2ZV3PC018636	SJAHY14V7PC019047	SJAHT2ZV8PC019376	SJAHT2ZV4PC019777
SJAHT2ZV2PC018174	SJAHY14V1PC018640	SJAHY14V0PC019052	SJAHT2ZV1PC019381	SJAH514V3PC019779
SJAHY14VXPC018183	SJAHT2ZV8PC018647	SJAHY14V1PC019061	SJAHT2ZV7PC019384	SJAHY14VXPC019785
SJAHY14V0PC018192	SJAHY14V4PC018650	SJAHT2ZV2PC019065	SJAHT2ZV8PC019393	SJAH514V5PC019797
SJAHT2ZVXPC018195	SJAHT2ZV1PC018652	SJAHY14VXPC019074	SJAHT2ZV5PC019402	SJAHT2ZV8PC019801
SJAHT2ZV6PC018209	SJAHT2ZV9PC018656	SJAHY14V5PC019077	SJAHY14V9PC019406	SJAHT2ZV0PC019808
SJAHT2ZV8PC018230	SJAHY14V9PC018675	SJAHY14V7PC019081	SJAHY14V6PC019413	SJAHT2ZV8PC019815
SJAHY14V6PC018231	SJAHY14V2PC018677	SJAHY14V6PC019086	SJAHY14V6PC019444	SJAHY14V6PC019816

INTERNAL

SJAHY14V2PC019831	SJAH514V7PC019963	SJAHY14V0PC020220	SJAHT2ZV1PC020384	SJAHT2ZVXPC020528
SJAHY14V3PC019840	SJAH514V4PC019970	SJAHL1ZV2PC020226	SJAHT2ZV7PC020390	SJAHT2ZV9PC020536
SJAHY14VXPC019849	SJAHT2ZV4PC019973	SJAHL1ZV5PC020236	SJAHT2ZV4PC020394	SJAH514VXPC020539
SJAHT2ZV5PC019853	SJAHL1ZV9PC019977	SJAHY14VXPC020239	SJAHT2ZV1PC020398	SJAHT2ZV8PC020544
SJAHY14V6PC019864	SJAHT2ZV1PC019980	SJAHL1ZV1PC020248	SJAHY14VXPC020399	SJAH514V6PC020554
SJAHY14V1PC019867	SJAHY14V9PC019986	SJAH514VXPC020251	SJAH514V0PC020419	SJAHL1ZV3PC020557
SJAH514V4PC019869	SJAHT2ZV0PC020005	SJAH514V5PC020254	SJAHT2ZV2PC020426	SJAHT2ZV8PC020561
SJAHY14V1PC019870	SJAHL1ZV5PC020009	SJAHY14V8PC020255	SJAHT2ZV4PC020430	SJAH514V0PC020565
SJAHY14V7PC019873	SJAH514V2PC020020	SJAHL14V5PC020258	SJAH514V0PC020436	SJAH514V3PC020589
SJAHT2ZV2PC019874	SJAHY14V2PC020039	SJAHT2ZV0PC020263	SJAHT2ZV7PC020437	SJAH514V1PC020591
SJAH514V3PC019880	SJAHT2ZV1PC020045	SJAHT2ZV4PC020265	SJAHT2ZV9PC020441	SJAH514V9PC020595
SJAHL14VXPC019882	SJAHT2ZV7PC020051	SJAHL1ZV7PC020268	SJAHT2ZV8PC020446	SJAHT2ZV0PC020599
SJAHL14V9PC019887	SJAH514V7PC020059	SJAHL1ZV7PC020271	SJAHT2ZV1PC020448	SJAHL14V5PC020602
SJAHY14V9PC019888	SJAH514V2PC020065	SJAHY14V0PC020279	SJAHT2ZV1PC020451	SJAH514VXPC020606
SJAHY14V6PC019900	SJAH514V6PC020067	SJAHY14V4PC020284	SJAHY14V3PC020454	SJAH514V1PC020610
SJAHY14V1PC019903	SJAHL1ZV2PC020081	SJAHY14V1PC020288	SJAH514V7PC020465	SJAH514V5PC020626
SJAH514V6PC019906	SJAH514V6PC020084	SJAHT2ZV0PC020294	SJAHT2ZV5PC020467	SJAH514V8PC020636
SJAHT2ZV4PC019908	SJAHT2ZV8PC020091	SJAHY14V0PC020301	SJAHT2ZV5PC020470	SJAH514V4PC020648
SJAHL14V0PC019910	SJAHT2ZV5PC020100	SJAH514V5PC020318	SJAHT2ZV7PC020471	SJAHT2ZV0PC020652
SJAHL14VXPC019915	SJAHY14V9PC020104	SJAH514V9PC020323	SJAHY14V6PC020478	SJAH514VXPC020654
SJAHY14V3PC019921	SJAHT2ZVXPC020111	SJAHL14V7PC020326	SJAHT2ZV8PC020480	SJAHT2ZV4PC020699
SJAHT2ZV2PC019924	SJAHY14V4PC020124	SJAHT2ZV0PC020330	SJAHT2ZV5PC020484	SJAH514VXPC020704
SJAH514V3PC019930	SJAHY14V2PC020137	SJAHY14V2PC020333	SJAHT2ZV0PC020487	SJAHT2ZV1PC020711
SJAHY14VXPC019933	SJAHL1ZV7PC020142	SJAHY14V9PC020345	SJAHY14V2PC020493	SJAHT2ZV9PC020715
SJAHT2ZV2PC019938	SJAH514V8PC020166	SJAHY14V6PC020352	SJAHT2ZV1PC020496	SJAHT2ZV6PC020722
SJAHL1ZV1PC019942	SJAHL1ZV5PC020169	SJAHY14V9PC020359	SJAHT2ZV7PC020499	SJAHT2ZV7PC020728
SJAHY14V1PC019948	SJAHL1ZV3PC020204	SJAHY14V4PC020365	SJAHT2ZV0PC020506	SJAHT2ZV5PC020730
SJAH514V0PC019951	SJAHL1ZV9PC020207	SJAHT2ZV1PC020367	SJAHT2ZV1PC020515	
SJAHY14V7PC019954	SJAHT2ZV7PC020213	SJAHY14V1PC020369	SJAHT2ZV7PC020518	
SJAH514V3PC019958	SJAHL1ZV1PC020217	SJAHY14V3PC020373	SJAHT2ZV5PC020520	