V O L V O

TRUCKS DEALER BULLETIN

To: General Managers, Service Managers, Service Technicians, Warranty Managers

From: Volvo Trucks – Service

Date: May 31, 2023

Subject: Service Literature Published and Released in May, 2023

Bulletin: SLV23-005

The following summarizes the service literature that has been published and/or revised for the month.

SERVICE NEWS

BULLETIN #	TITLE	COMMENTS
	None Issued	

TOOL BULLETINS

BULLETIN #	TITLE	COMMENTS
	None Issued	

TECHNICAL SERVICE BULLETINS

BULLETIN #	TITLE	COMMENTS
	None Issued	

SERVICE PROGRAMS

BULLETIN #	TITLE	COMMENTS
S2999	BEV A/C Compressor Inspection And Replacement	New
S3174	Transmission Bolt Replacement	New
S3252	Rocker Arm Adjustment	New
S7414	Field Test Software Removal	Revised
S7654	Drive Axle Oil Change	Revised

RECALLS

BULLETIN#	TITLE	COMMENTS
	None Issued	

^{© 2023} Volvo Group North America, LLC. CONFIDENTIAL - For limited distribution only to circulation list above. This bulletin, and any information herein, is subject to change by Company without notice. For the most current and accurate information, always refer to Trucks Dealer Portal for the electronic version of this document.

V O L V O

TRUCKS DEALER BULLETIN

CASE BASED REASONING (CBR)

NEW SOLUTIONS

SOLUTION #	TITLE	
CBR-2277	277 Battery Electric Vehicle (BEV) Sub Hardware Programming	

UPDATED SOLUTIONS

SOLUTION	TITLE	COMMENTS
CBR-474	Diagnostic Trouble Code (DTC) P215A-64, Fault Code SPN 84 FMI 19	Corrected mismatch in operations listed.
CBR-2255	Battery Electric Vehicle (BEV) Cab Heater Diagnostics	Updated temperature specifications.
CBR-2229	Automated Manual Transmission (AMT) Transmission Kickdown Mode	Updated the accessory kit part number.
CBR-331	Model Year 2017 to Current - Fuel Filter Change (Primary And Secondary) For The EM - USA17 Emission Engines	Updated title to include model years 2017 to current.
CBR-901	Remote Control Central Door Lock, Programming; Key Fob Cannot Be Programmed Or Does Not Work After Programming - Model Year 2018 And Newer	Withdrawn for review of information.
CBR-2050	Diagnostic Trouble Code (DTC) P225C00 : NOx1 Sensor Stuck High - US17+OBD2019 And Newer Emissions	Solution withdrawn. Information superseded by CBR-2191.