
Service Information



To All Dealer Partners,

There is a new safety-function at J533 which blocks the adaption of the new battery using the Adapting A-Battery function test plan in ODIS. We already implemented a solution and adapted a new test program algorithm. Please load the attached hotfix A_2.31.0_Ticket_00122135_12VBatteryAdaption_20230524-074159 and perform the function test again.

The VAS tester must be on the latest and greatest ODIS software version Application 11.0.01 and Audi Brand 2.31.00.

For questions or concerns, please reach out to David Provonche, 248-754-6091.

extern.dave.provonche@audi.com

Audi GFF / ODIS Validation / Service42 Research

VWGoA, Inc.

Product Quality & Technical Service

© 2023 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.