



Preliminary Information

PIP5920 Ticking Noise From Engine 5.5L RPO LT6

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Corvette	2023	All	All	5.5L LT6	All

Involved Region or Country	North America
Condition	A customer may have a concern that may be described as a ticking or tapping noise from the upper end of the engine. It may also be found that the noise is most noticeable at idle with engine at operating temperature.
Cause	Under Investigation

Correction:

Compare the concern with the sound file in this PI.

(SOUND FILE HERE) [The sound file can be accessed in the SI version of this PI or in the attachments section below.](#)

If the noise has been determined to be the same as what is in the attached sound recording:

At this time the concern is under engineering investigation, once a repair has been established this PI will be updated or changed to a bulletin.

No durability issues have been identified with this concern and customer can drive the vehicle until a repair is available.

If the noise has been determined to NOT be the same as what is in the attached sound recording, please review the latest version of PIP5869 for a list of serviceable components in conjunction with following SI diagnostics.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4089008*	Review attached sound file	0.3
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	5/01/2023 - Created.



GENERAL MOTORS