



Preliminary Information

PIT6009A Front License Plate Bracket Missing at PDI

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Blazer	2023	1/30/2023	4/19/2023	All	All

Involved Region or Country	North America
Additional Options (RPO)	VK3
Condition	It may be discovered when performing the PDI on a vehicle that the front license plate bracket is not included with the loose items. If the vehicle was delivered to a state that requires a front license plate or has option code VK3 it should be included.
Cause	Plant packaging error. This is NOT a transportation issue.

Correction:

Order license plate bracket part # 42708218.

Note: The labor claim below has no time included due to labor already being paid with PDI. Please file the labor claim to allow for payment of the bracket.

You may need to place a SPAC case on the order.

Parts Information

Description	Part Number	Quantity
License Plate Bracket	42708218	1

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Time
0588718*	Install Missing Front License Bracket	0.0 Hr.
	*This is a unique Labor Operation for Bulletin use only.	

Version History

Version	2
Modified	05/02/2023 - Created on. 05/31/2023 - Updated to add labor operation.



GENERAL MOTORS