GLOBAL SAFETY FIELD INVESTIGATIONS DCS6609 URGENT - DISTRIBUTE IMMEDIATELY

Date: June 26, 2023

- Subject: N232408020 Customer Satisfaction Program Missing Front License Plate Bracket
- Models: 2023 Chevrolet Blazer Equipped with License Plate Front-Frt Mounting Pkg (RPO VK3)
- To: All General Motors Dealers

General Motors is releasing Customer Satisfaction Program N232408020 today. The total number of U.S. vehicles involved is approximately 339. Please see the attached bulletin for details.

Customer Letter Mailing

The customer letter mailing will begin on July 11, 2023.

Global Warranty Management (GWM)

The Required Field Action section on the Investigate Vehicle History (IVH) screen will be updated June 26, 2023. A list of vehicles in dealer inventory is attached to this message.

END OF MESSAGE

GLOBAL SAFETY FIELD INVESTIGATIONS

Customer Satisfaction Program

N232408020 Missing Front License Plate Bracket



Release Date: June 2023

Revision: 00

Attention: This program is in effect until July 31, 2025.

		Model Year				
Make	Model	From	То	RPO	Description	
Chevrolet	Blazer	2023	2023	VK3	LICENSE PLATE FRONT-FRT MOUNTING PKG	

Involved vehicles are marked "Open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

	Condition	Certain 2023 model year Chevrolet Blazer vehicles may have been shipped from the assembly plant without the front license plate bracket.	
- [Correction	Dealers will install the front license plate breaket	

Correction Dealers will install the front license plate bracket.

Parts

Quantity	Part Name	Part No.
1	BRACKET-FRT LIC PLT	42708218
4	SCR-LARGE DOMED WASH HD TY1A CR	11609539
4 BOLT/SCREW-LICENSE PLATE SLOTTED/CROSS RECESS TAPING		09423101


It is estimated that only 339 involved vehicles will require parts to be replaced. Due to the small number of vehicles anticipated that will need this fix and the limited initial parts availability, dealers are encouraged not to order these parts for use as shelf stock.

Reminder: Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

Warranty Information

Labor	Description	Labor	Trans.	Net
Operation		Time	Type	Item
9106902	Install License Plate Bracket	0.2	ZFAT	N/A

Service Procedure




Customer Satisfaction Program

N232408020 Missing Front License Plate Bracket



6376233



- 1. Center license plate bracket with the middle of the front emblem at the bottom of the upper grille.
- 2. While holding the bracket in place, install the 4 self-tapping screws (2) in the bracket to the grille.
- 3. Be sure the 4 bolts (1) for securing the license plate are either installed on the bracket or given to the customer.

Dealer Responsibility

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this program <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

Dealers are to service all vehicles subject to this program at no charge to customers, regardless of mileage, age of vehicle, or ownership, through July 31, 2025. Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the involved vehicle listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A copy of the customer letter is provided in this bulletin for your use in contacting customers. Program follow-up cards should not be used for this purpose since the customer may not as yet have received the notification letter.



In summary, whenever a vehicle subject to this program enters your vehicle inventory or is in your facility for service through July 31, 2025, you must take the steps necessary to be sure the program correction has been made before selling or releasing the vehicle.

Dealer Reports - For USA & Export

For dealers with involved vehicles, a listing has been prepared and will be available through GM GlobalConnect Maxis Field Action Reports or sent directly to export dealers. The Inventory tab of the dealer reports will contain VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will contain customer names and addresses from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this field action may be a violation of law in several states.

Customer Notification

USA & Canada - General Motors will notify customers of this program on their vehicle (see copy of customer letter included with this bulletin).

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



We Support Voluntary Technician Certification



July 2023

This notice applies to your vehicle, VIN:

Dear General Motors Customer:

We have learned that your 2023 model year Chevrolet Blazer may have been shipped from the assembly plant without the front license plate bracket.

Your satisfaction with your Blazer is very important to us, so we are announcing a program to prevent this condition or, if it has occurred, to fix it.

What We Will Do: Your GM dealer will install the front license plate bracket. This service will be performed for you at no charge until July 31, 2025. After that, any applicable warranty will apply.

What You Should Do: To limit any possible inconvenience, we recommend that you contact your dealer as soon as possible to schedule an appointment for this repair. By scheduling an appointment, your dealer can ensure that the necessary parts will be available on your scheduled appointment date.

If you have any questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

For the hearing or speech impaired, please contact our Customer Assistance Center using the Telecommunication Relay Service by dialing 711 then providing the appropriate Customer Assistance Center number for your vehicle.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-222-1020	711 / 1-800-833-2438
Puerto Rico – English	1-866-467-9700	
Puerto Rico – Español	1-866-467-9700	
Virgin Islands	1-866-467-9700	

We truly appreciate you taking the time to remedy your vehicle as we know your time is valuable. We want you to know that we will do our best, throughout your ownership experience, to ensure that your Chevrolet Blazer provides you many miles of enjoyable driving.

Neelie O'Connor Global Executive Director Customer Experience Operations

N232408020