

**Audi On-car analysis list from June, 2 2023**

**Please contact Audi Helpline before attempting repair**

**All topics have associated worksheets to be filled out and attached to the TAC ticket. Worksheets can be found at: [ServiceNet](#)>>[Technician References](#)>>[Vin-4-Pin](#)>>[Worksheets](#)**

	Models	MY	Engine	Trans	Topic	Topic details
PT	Q3	2020-2021	All	All	Coolant warning Lamp	Customer states they receive a low coolant warning in the cluster. Coolant level appears to be full in the reservoir  <ul style="list-style-type: none"> <li>Case does not relate to TSB 2061918</li> <li>Photo showing reservoir level</li> <li>Complete reservoir, connector and 4 inch harness section</li> </ul>
	All models with 3.0L engine (EA839)	2021-2023	3.0L (EA839)	All	Abnormal/no sound from engine sound generator	<ul style="list-style-type: none"> <li>Video/ sound recording of abnormal noise/ customer complaint from inside the vehicle before repair.</li> <li>Video/ sound recording while running sound actuator test</li> <li>Upload GFF log with executed test and relevant DTCs to GFF paperless</li> <li>Video/ sound record of noise from inside the vehicle after repair.</li> </ul>
	Q3	2020-2023	All	All	Q3 oil pan leak	Oil leak found coming from the oil pan.
EL	Q5	2023	Any	Any	Q5 - Belt noise from Starter Generator	Noise is present from the starter generator during starting or while running. <ul style="list-style-type: none"> <li>An audio/video recording of the noise</li> <li>Ambient conditions of the complaint: Temperature / Humidity</li> <li>Does the complaint happen over a larger temperature range? Or just when it is cold for example.</li> </ul>
	Q3	2022	2.0	Any	Boost pressure sensor	Check engine lamp is on, DTC (s) P010600, P023600, P023700, P023800  Documentation needed: <ul style="list-style-type: none"> <li>Wiggle test harness</li> <li>Check pin fitment and pin drag</li> <li>Check circuit resistance (if needed)</li> <li>Photos of findings</li> <li>Q3 Boost pressure sensor worksheet</li> </ul>
	All	2023	Any	Any	USB trim detached	USB trim panel is pushed in, loose or detached from center console.
BD	e-tron Quattro e-tron SB	2021-2022	Any	Any	Noise from Front Door Trim Panel	Noise from front door trim panel while driving <ul style="list-style-type: none"> <li>Video of noise before repair is performed</li> <li>Photos of repair</li> </ul>
	A5	2021-2022	Any	Any	Noise from Front Door speaker Grill	Photo of both sides of the thorax/side airbag wire harness label (Figures 2, 3).